

Hydrant Inspection Report

Docket No. 97-0606

ICC Staff Ex. 3.00

Schedule 3.03, pg. 2 of 2

System: **Highland Shores Water Company**

		Static	Flow	Gals.	Minutes	
Hydrant #	Location	Pressure	Pressure	per minute	Flowed	Comments
11	Between Memory & Shady	60	25	830	8	
	on Thompson					
15	BetweenMemory & Elm					
	on Lake Vista	70	20	730	23	a) Replace - upper barrel crack.
9	Between Sunset & Shady	75	20	670	7	a) Hydrant requires painting;
	on Lake Vista					
12	Between Memory & Shady	83	60	750	7	a) Hydrant requires painting;
	on Lake Shore Drive					
6	Between Ramble & Sunset	83	40	750	10	a) Hydrant requires painting;
	on Lake Shore Drive					
4	Between Acorn & Ramble					a) Replace - Not operatable
	on Lake Vista					
FV39				340	7	a) Install flushing hydrants.
FV 1				340	5	a) Install flushing hydrants.
FV 2				340	5	a) Install flushing hydrants.
FV 3				370	3	